

## Possible causes for the Pioneer anomaly

- Gravity influence of the Kuiper Belt
- Errors in accepted physical values of the Earth's orientation, precession, and nutation.
- Thermal radiation of the spacecraft itself
- spacecraft gas leaks
- Momentum loss due to signals send back to Earth
- Unknown systematic errors in the spacecraft measuring devices